




## Schnappmutter -

### Ohne Gewinde, Form M-P

- Material: Federstahl verzinkt blau
- Oberfläche ROHs konform verzinkt blau




#### Form M



Teile-Nr.	∅	p	A ±0,3	B ±0,3	C ±0,3	s
[U29-170]	2,9	1,7	10	10	4,6	0,4
[U42-125]	4,2	1,0-2,0	16,5	12	7	0,7

#### Form N




Teile-Nr.	∅	p	A ±0,3	B ±0,3	C ±0,3	s
[U29-354]	2,9	3,4-4,0	10,5	7,5	5	0,5

#### Form O



Teile-Nr.	∅	p	A ±0,3	B ±0,3	C ±0,3	s
[U48-360]	4,8	3,5	17	11	10	0,7

#### Form P



Teile-Nr.	∅	p	A ±0,3	B ±0,3	C ±0,3	s
[U48-135]	4,8	1,0-3,0	17	11	9	0,5